LOC I-OEH	APP CRS	Rwy Idg	10002
109.7	285°	TDZE	142
		Apt Elev	146

BALTIMORE/ WASHINGTON INTL THURGOOD MARSHALL (BWI)

ILS or LOC RWY 28

DME Required.
▼ ** RVR 1800 authorized with the use of FD or AP or HUD to DA.
△ ZIXUS Fix mimimums: For inoperative MALSR, increase S-LOC 28 Cat D visibility to RVR 5000.

MALSR (A5)

MISSED APPROACH: Climb to 2500 via BAL R-286 to COLUM/BAL 11.4 DME/ RADAR and hold.

ATIS	POTOMAC APP CON	BALTIMORE TOWER	GND CON	CLNC DEL
115.1 127.8	119.7 290.475	119.4 257.8	121.9	118.05

ALTERNATE MISSED APCH FIX
WESTMINSTER 117.9 EMI Chan 126
079° 359° R-179

RADAR REQUIRED

1549 1504 670 731 685 958 604 281± 242± 340 281 201 741 555 233 290 560 591 372 533 1049

286° 106° R-286 R-286 COLUM BAL 11.4 RADAR

ZIXUS BAL 2.3

JURTI BAL 5.9 RADAR

(IF) HURTZ BAL 12.1 RADAR

2000 285° (6.2) 105°

BALTIMORE 115.1 BAL Chan 98

LOCALIZER 109.7 I-OEH

MSA BAL 25 NM
2600
090°
2100
360°

NE-3, 31 MAY 2012 to 28 JUN 2012

NE-3, 31 MAY 2012 to 28 JUN 2012

ELEV 146 D TDZE 142



TDZ/CL Rwys 10 and 33L
REIL Rwys 15L and 33R
HIRL all rwys

FAF to MAP 5.6 NM					
Knots	60	90	120	150	180
Min:Sec	5:36	3:44	2:48	2:14	1:52



VGSI and ILS glidepath not coincident (VGSI Angle 3.00/TCH 60).

CATEGORY	A	B	C	D
S-ILS 28	**342/24 200 (200-½)			
S-LOC 28	820/24 678 (700-½)		820-1½ 678 (700-1½)	820-1¾ 678 (700-1¾)
CIRCLING	820-1 674 (700-1)		820-2 674 (700-2)	820-2¼ 674 (700-2¼)
ZIXUS FIX MINIMUMS				
S-LOC 28	460/24 318 (400-½)			460/40 318 (400-¾)
CIRCLING	640-1 494 (500-1)		640-1½ 494 (500-1½)	740-2 594 (500-2)

BALTIMORE/WASHINGTON INTL THURGOOD MARSHALL (BWI)
ILS or LOC RWY 28

39°11′N-76°40′W