COLNS TRANSITION (COLNS.GAVNN4):
HENDERSON TRANSITION (HNN.GAVNN4):

From over GAVNN on track 308° to KNEDY, thence as depicted to OGIRE.

Landing South: Expect radar vectors to final approach course prior to OGIRE.
Landing North, East, West: Expect radar vectors to final approach course prior to AAJAY.

LOST COMMUNICATIONS:

At OGIRE fly heading 270°, maintain 6000; intercept and execute ILS RWY 18L approach. If unable, proceed direct to CVG VORTAC and hold NE, RT, 239° inbound, maintain 6000.

At KNEDY fly heading 270°, maintain 6000; intercept and execute ILS RWY 36R approach. If unable, proceed direct to CVG VORTAC and hold NE, RT, 239° inbound, maintain 6000.





SE-1, 05 MAR 2015 to 02 APR 2015

GAVNN FOUR ARRIVAL (RNAV)
(GAVNN.GAVNN4) 11349
COVINGTON, KENTUCKY
CINCINNATI/ NORTHERN KENTUCKY INTL