ALPIN ONE DEPARTURE



TAKEOFF MINIMUMS

Rwy 1: NA - ATC request.

Rwy 19: Standard with minimum climb of 341′ per NM to 15000.

TAKEOFF OBSTACLE NOTES

RWY 19: Bush 485′ from DER, 513′ right of centerline, 15′ AGL/6428′ MSL.

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 19: Climb via JAC R-192 to cross KICNE INT/JAC 27 DME at or above 15000. Thence. . . .

. . . . via (transition) or (assigned route). Expect further clearance to filed altitude 10 minutes after departure.

IDAHO FALLS TRANSITION (ALPIN1.IDA): From over KICNE INT via IDA R-096 to IDA VOR/DME.

SWEAT TRANSITION (ALPIN1.SWEAT): From over KICNE INT via BPI R-299 to BPI VOR/DME, then via BPI R-080 to SWEAT INT.

NW-1, 02 MAY 2013 to 30 MAY 2013