HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated.

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
DAYTONA BEACH, FL		
DAYTONA BEACH INTL (DAB)	HS 1	Int of Twy W and Twy S.
FORT LAUDERDALE, FL		
FORT LAUDERDALE EXECUTIVE (FXE)	HS 1	Int of Twy E and Rwy 09 at the apch end.
	HS 2	Int of Twy B and Rwy 09-27.
	HS 3	Int of Twy A and Rwy 13-31.
	HS 4	Int of Twy C, Twy B and Rwy 13-31.
	HS 5	Int of Twy B and Rwy 13-31.
FORT LAUDERDALE, FL		
FORT LAUDERDALE-HOLLYWOOD INTL (FLL)	HS 1	Twy E at Rwy 09L-27R.
	HS 2	Twy D at Rwy 09L-27R.
	HS 3	Twy Q at Rwy 09L-27R.
	HS 4	Twy departure risk. Twy B instead of Rwy 09L.
	HS 5	Twy D4: wrong rwy departure risk.
FORT MYERS, FL		
PAGE FIELD (FMY)	HS 1	Twy A intersects Twy A2 and Twy D. Do not use Twy A2 to the rwy unless instructed.
	HS 2	Multiple twy intersections.
FORT MYERS, FL		
SOUTHWEST FLORIDA INTL (RSW)	HS 1	Twy G1 is directly aligned with Twy F2.
	HS 2	When ldg Rwy 06, Twy F6 high speed exit sign is immediately before the Twy F5 reverse high speed.
GAINESVILLE, FL		
GAINESVILLE RGNL	HS 1	Rwy 11 Apch Hold Position.
	HS 2	Rwy 07 and Rwy 11 apch ends.
	HS 3	Twy A1 and Twy B lead to Rwy 25 and Rwy 29.
HOLLYWOOD, FL		
NORTH PERRY (HWO)	HS 1	Southbound on Twy D for Rwy 28R departures.
	HS 2	The hold line for Rwy 01L is also the hold line for Rwy 10R.
	HS 3	Aircraft taxiing on Twy L westbound to depart on Rwy 01L-19R.
MIAMI, FL		
KENDALL-TAMIAMI EXECUTIVE (TMB)	HS 1	Twy H and Twy E hold lines are in close proximity to Rwy 13-31.

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

04 FEB 2016 to 03 MAR 2016

04 FEB 2016 to 03 MAR 2016

HOT SPOTS

(CONTINUED)

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
MIAMI, FL		
MIAMI INTL (MIA)	HS 1	Short twy risk.
	HS 2	Short twy risk.
	HS 3	Rwy 27 and Rwy 30 wrong rwy departure risk.
	HS 4	Short twy between rwys.
	HS 5	Multiple rwy ends close together. Some hold lines dependent upon rwy in use.
MIAMI, FL		
OPA-LOCKA		
EXECUTIVE (OPF)	HS 1	Surface painted LOCATION and DIRECTION signs ONLY.
NEW SMYRNA BEACH, FL		
NEW SMYRNA		
BEACH MUNI (EVB)	HS 1	Twy E and Rwy 25 and Rwy 20.
ORLANDO, FL		
EXECUTIVE (ORL)	HS 1	Twy K and Twy A.
	HS 2	Rwy 25 and Twy E.
	HS 3	Rwy 07 and Twy A3.
ORLANDO SANFORD		
INTL (SFB)	HS 1	Twy C is beyond the Rwy 09C APCH hold sign and marking.
	HS 2	Hold line for Rwy 09R on Twy R northbound is adjacent to Twy S.
ST. AUGUSTINE,FL		
NORTHEAST FLORIDA		
RGNL (SGJ)	HS 1	Maint vigilance ramp/twy close proximity to rwy.
SARASOTA/BRADENTON		
SARASOTA/BRADENTON		
INTL (SRQ)	HS1	Intersection of Rwy 14-32 and Rwy 4-22.
STUART, FL		
WITHAM FIELD (SUA)	HS 1	Intersecting rwys, wrong rwy departure risk.
	HS 2	Rwy 12 and Twy A1.
WEST PALM BEACH, FL		
PALM BEACH INTL (PBI)	HS 1	Rwy 10L and Twy L.
	HS 2	Missing left turn from Twy F to Twy L.
	HS 3	Missing turn onto Twy G results in mid-field incursion.

*See appropriate A/FD, Alaska or Pacific Supplement HOT SPOT table for additional information.

04 FEB 2016 to 03 MAR 2016