


# AIRPORT DIAGRAM

AL-330 (FAA)

PORTLAND INTL (PDX)  
PORTLAND, OREGON

NW-1, 12 JAN 2012 to 09 FEB 2012



CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.  
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

# AIRPORT DIAGRAM

PORTLAND, OREGON  
PORTLAND INTL (PDX)

NW-1, 12 JAN 2012 to 09 FEB 2012