## HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams until such time the increased risk has been reduced or eliminated

CITY/AIRPORT	HOT SPOT	DESCRIPTION*
1		

DOVER, DE

DOVER AFB (DOV) HS<sub>1</sub> Intersecting of Rwy 01-19, Rwy 14-32 and Twy D between the

runways can create confusion. Query tower if lost or need

help.

HS<sub>2</sub> Rwy 01-19 between Twy B and Twy E has had an increased

number of rwv incursions.

HS 3 Rwy 14-32 between C Twy has had an increased number of rwy

incursions.

EASTON, MD

EASTON/NEWNAM FLD (ESN) HS 1 Twy A and Twy B int in close proximity to the rwy.

FREDERICK, MD

FREDERICK MUNI (FDK) HS 1 Int of Twy A and Twy B.

HS 2 Potential for inadvertent entry onto Rwy 30. HS 3 Potential for inadvertent entry onto Rwy 23.

HAGERSTOWN, MD

HAGERSTOWN RGNL/

RICHARD A HENSON FLD (HGR) HS 1 Maintain vigilance congestion area and close proximity to rwys.

NEWPORT NEWS, VA

22 FEB 2024 to 21 MAR 2024

NEWPORT NEWS/WILLIAMSBURG

INTL (PHF) HS<sub>1</sub> Int of Rwy 07-25 and Rwy 02-20.

HS2 Rwy 07 and Rwy 02 thlds in close proximity. RICHMOND, VA

RICHMOND INTL (RIC) HS<sub>1</sub>

Wrong rwy departure risk. Frequent rwy crossings due to

aircraft exiting Rwy 34.

WASHINGTON DO

MANASSAS RGNI / HARRY P

DAVIS FLD (HEF) HS 1 Twy K, Twy B3 and Rwy 16L-34R.

RONALD REAGAN WASHINGTON

NTL (DCA) HS 1 Twy N, Twy K, Twy L, and Twy J, Rwy 15-33.

Maintain awareness of Hold Line position for Rwy 19 from the HS 2

Hold Bay and while approaching Rwy 19 on Twy J.

HS 3 Twy J, Twy G, Twy M and Rwy 01-19.

WILMINGTON, DE

HS<sub>1</sub> NEW CASTLE (ILG) Twy F intersects Rwy 09-27 which is in close proximity to the thId

of Rwv 14-32.

<sup>\*</sup>See appropriate Chart Supplement HOT SPOT table for additional information.