


LOM MW 223	APP CRS 085°	Rwy Idg TDZE Apt Elev	N/A N/A 957
----------------------	------------------------	-----------------------------	--

NA If local altimeter setting not received, use James M Cox Dayton Intl altimeter setting and increase all MDAs 60 feet.




MISSED APPROACH: Climb to 2500, then climbing right turn to 3000 direct MW LOM and hold.

ASOS 118.375	COLUMBUS APP CON 126.5 327.125	CLNC DEL 119.4	UNICOM 122.8 (CTAF) 0
------------------------	--	--------------------------	--



EC-2, 08 JAN 2015 to 05 FEB 2015

EC-2, 08 JAN 2015 to 05 FEB 2015



CATEGORY	A	B	C	D	FAF to MAP 4.4 NM					
CIRCLING	1480-1	523 (600-1)	1520-1½ 563 (600-1½)	1660-2¼ 703 (800-2¼)	Knots	60	90	120	150	180
					Min:Sec	4:24	2:56	2:12	1:46	1:28