22 FEB 2024 to 21 MAR 2024

HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training. Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and tabulated in the list below with a brief description of each bot spot. Hot spots will remain charted on airport diagrams.

until such time the increased risk ha		of each hot spot. Hot spots will remain charted on airport diagrams eed or eliminated.
CITY/AIRPORT	HOT SPOT	DESCRIPTION*
BRANSON, MO		
BRANSON (BBG)	HS 1	Ramp area exits on to rwy.
CAPE GIRARDEAU, MO	HS 2	Twy turn around at end of rwy. Frequent back taxi operations.
CAPE GIRARDEAU, MO	I) HS 1	Area not visible from the twr.
OAI E GINANDEAG NOIVE (OG	HS 2	Aircraft ldg Rwy 10 sometime mistake Rwy 02-20 as Twy D.
CEDAR RAPIDS, IA	1.0 2	The carriag (th) to combine modulo (th) 52 25 do (th) 5.
THE EASTERN IOWA (CID)	HS 1	Frequent aircraft and vehicle rwy crossings.
, ,	HS 2	Int rwys.
COLUMBIA, MO		
COLUMBIA RGNL (COU)	HS 1	Confusing twy int.
COUNCIL BLUFFS, IA		D 44 4 171 H 0715
COUNCIL BLUFFS MUNI (CBF)		Rwy 14 not visible. Use CTAF.
DEC MOINES IA	HS 2	Rwy 18 not visible. Use CTAF.
DES MOINES, IA DES MOINES INTL (DSM)	HS 1	Rwy 05-23 crossings on Twy D.
DES MOINES INTE (DSM)	HS 2	Rwy 13-31 crossings on Twy P.
	HS 3	The apch end of Rwy 05 at Twy P has limited visibility from the twr.
DUBUQUE, IA		, , , , , , , , , , , , , , , , , , , ,
DUBUQUE RGNL (DBQ)	HS 1	Apch ends of rwys in close proximity.
	HS 2	Rwy 13-31 in close proximity to ramp non-movement area at
		Twy D.
	HS 3	Rwy 13-31 in close proximity to ramp non-movement area at
FORT BORDS IA		Twy C.
FORT DODGE, IA	110.4	Int an tracket adapt a new
FORT DODGE RGNL (FOD)	HS 1	Int on twy just prior to rwys.
FORT LEONARD WOOD, MO		
WAYNESVILLE-ST ROBERT		
RGNL FORNEY FLD (TBN)	HS 1	Single twy access to rwy. Frequent back-taxi ops.
		g
JOPLIN, MO		
JOPLIN RGNL (JLN)	HS 1	Rwy 13-31 hold short markings on Twy E.
	HS 2	Twy D int with Twy E and Rwy 13-31.
	HS 3	Pilots taxiing to Rwy 31 via Twy C often confuse the non-standard
		location of the Rwy 31 Holding Position for an ILS Holding
		Position. There is no ILS for Rwy 31. The Rwy 31 Holding Position is a non-standard configuration and is necessary due to the
		dthr on Rwy 31 and the requirement to have aircraft outside of
		the Object Free Area.
KANSAS CITY, MO		

CHARLES B. WHEELER

DOWNTOWN (MKC) HS 1 Twy G int with Rwy 04-22.

HS 2 Confusing twy int.

HS 3 Crossing Rwy 04 at Twy F, Twy A and Twy B.

(SEE CONTINUATION PAGE FOR MORE LISTINGS)

22 FEB 2024 to 21 MAR 2024

HOT SPOTS

		(CONTINUED)
CITY/AIRPORT	HOT SPOT	DESCRIPTION*
KANSAS CITY INTL (MCI)	HS 1 HS 2 HS 3	Twy E and Twy F int with Rwy 09-27. Twy C and Twy D int with Rwy 01R-19L. Expect congestion Twy B near main terminal & Twys A7, A8, A9, A10, G and taxi-lanes S, M, N. Do not enter terminal apron without approval.
KIRKSVILLE, MO	HS 4	Misalignment risk - Twy A at Rwy 01L-19R.
KIRKSVILLE RGNL (IRK)	HS 1	Turf rwy taxi route via Rwy 18-36.
MASON CITY, IA MASON CITY MUNI (MCW)	HS 1	Twy leads to multiple rwys.
ST JOSEPH, MO		
ROSECRANS MEML (STJ)	HS 1 HS 2	Closely located rwys. Back taxi required for full length Rwy 13.
ST LOUIS, MO ST LOUIS LAMBERT INTL (ST	_) HS 1	Turn onto Twy S from Twy F for Rwy 12L.
SIOUX CITY, IA SIOUX GATEWAY/BRIG		
GENERAL BUD DAY FLD (SUX	() HS 1 HS 2	Area not visible from the twr. Twy A near the ARFF bldg and Twy G are not visible from ATCT.
SPRINGFIELD, MO SPRINGFIELD-BRANSON		
NTL (SGF)	HS 1 HS 2	Twr blind spot on movement area. INT of Twy D and Twy N is in close proximity to Rwy 02-20 and Rwy 14-32. Use caution to insure proper turns to avoid entering the rwy without a clearance.
WATERLOO, IA WATERLOO RGNL (ALO)	HS 1	Twy int near rwys.
WATERLOO RONE (ALO)	HS 2	Twy A at Rwy 12-30

HS 2 Twy A at Rwy 12-30.

*See appropriate Chart Supplement HOT SPOT table for additional information.